## **2006 ANNUAL REPORT**

ANDALEX RESOURCES, INC.
CENTENNIAL MINESITE
C/007/019

File in:

| Confidential |
| Shelf |
| Expandable |
| Refer to Record No (15 | Date[4/05/07 |
| In C/(207//014 | 2001 | Incoming) |
| For additional information

## 2006 ANNUAL REPORT

To enter text, click in the box and type your response. If a box already contains an entry select the entry and type the replacement. You can use the tab key to move from one field to the next. To select a check box, click in the box or type an x.

#### **GENERAL INFORMATION**

| Permitte Name                   | Andalex Resources, Inc.                         |
|---------------------------------|---|
| Mine Name                       | Centennial Minesite                             |
| Operator Name                   |   |
| (If other then permittee)       |   |
| Permit Expiration Date          | January 5, 2012                                 |
| Permit Number                   | C/007/019                                       |
| Authorized Representative Title | Dave Shaver, Resident Agent                     |
| Phone Number                    | (435) 888-4017                                  |
| Fax Number                      | (435) 888-4002                                  |
| E-mail Address                  | dshaver@coalsource.com                          |
| Mailing Address                 | P.O. Box 1077, Price, Utah 84501                |
| Designated Representative       | Dave Shaver                                     |
| Resident Agent                  | Dave Shaver                                     |
| Resident Agent Mailing Address  | P.O. Box 1077, Price, Utah 84501                |
| Number of Binders Submitted     | (2) 1-Salt Lake Office and 1-Price Field Office |

#### **IDENTIFICATION OF OTHER PERMITS**

Identify other permits that are required in conjunction with mining and reclamation activities.

| Permit Type           | ID Number   | Description  | Expiration Date |
|-----------------------|-------------|--------------|-----------------|
| MSHA Mine ID(s)       | 42-01474    | Pinnacle     | N/A             |
| , ,                   | 42-01750    | Apex         | N/A             |
|                       | 42-02028    | Aberdeen     | N/A             |
| MSHA Impoundment(s)   | N/A         |              |                 |
| NPDES/UPDES Permit(s) | UT0025674   | UPDES Permit | 11/30/2011      |
| PSD Permit(s) (Air)   | DAQE-997-96 | Centennial   | N/A             |
| Other                 |             |              |                 |
|                       |             |              |                 |
|                       |             |              |                 |
|                       |             |              |                 |
|                       |             |              |                 |

| 006 ANNUAL REPO   | ORT                              |                 |                                | Page 2   |
|---|----------------------------------|-----------------|--------------------------------|--|
| <u> </u>  | d inspection :<br>t the Division | n. Specify when | _                              | nd udder the approved plan that must be<br>n is included as Appendix A to this report  |
|   | <b>Required</b><br>Yes No        | Included or o   | n file with DOGM<br>On File    | Comments   |
| Excess Spoil Piles Refuse Piles   |                                  |                 |                                | Annondist  |
| Impoundments Other  |                                  |                 |                                | Appendix A   |
|   | nical data and<br>to the Divisi  | d information a | s required under th            | ne approved plan, which must be<br>on is included as Appendix B to this report         |
| Technical Data:   | Required<br>Yes No               |                 | or on file with DOG<br>On file | M Comments   |
| Climatological Subsidence Monitoring Vegetation Monitoring Raptor Survey Soils Monitoring Water Monitoring First quarter Second quarter Third quarter Third quarter Fourth quarter Geological / Geophysical Engineering Non Coal Waste / Abandoned Underground Equipment* |                                  |                 |                                | Appendix B   |
| Other Data  |                                  |                 |                                |  |
|   |                                  |                 |                                | must be submitted that includes a map<br>were any hazardous or toxic materials and any |

revision to the PHC as necessary.

#### LEGAL, FINANCIAL, COMPLIANCE AND RELATED INFORMATION

Change in administration or corporate structure can often bring about necessary changes to information found in the mining and reclamation plan. The Division is Requesting that each permittee review and update the legal, financial, compliance and related information in the plan as part of the annual report. Please provide the Department of Commerce, Annual Report of Officers, or other equivalent information as necessary to ensure that the information provided in the plan is current. Provide any other change as necessary regarding land ownership, lease acquisitions, legal results from appeals of violations, or other changes as necessary to update information required in the mining and reclamation plan. Include certified financial statements, audits or worksheets, which may be required to meet bonding requirements. Specify whether the information is currently on file with the Division or included as Appendix C to the report.

| Legal / Financial Update                          | Requ<br>Yes | i <b>red</b><br>No | Included or of Included | on File with DOGM On file | Comments |
|---|-------------|--------------------|-------------------------|---------------------------|----------|
| Department of Commerce,<br>Annual Report Officers |             |                    |                         | $\boxtimes$               |          |
| Other   | - 📙         |                    |                         |                           |          |
|   |             |                    |                         |                           |          |

#### MINE MAPS

Copies of mine maps, current and up-to-date through at least December 31, 2006, are to be provided to the Division as Appendix D to this report in accordance with the requirements of R 645-301-525.240. These map copies shall be made in accordance with 30 CFR 75.1200 as required by MSHA. Upon request, the Division shall keep mine maps confidential. Please provide a CD.

| Map Number(s) | Map Title/ Description | Confidential |
|---------------|------------------------|--------------|
|               |                        | Yes No       |
| Appendix D    | Aberdeen Mine          | $\square$    |
| Appendix D    | Pinnacle Mine          |              |
|               |                        |              |
|               |                        |              |
|               |                        |              |
|               |                        |              |
|               |                        |              |
|               |                        |              |
|               |                        |              |
|               |                        |              |
|               |                        |              |

| 006 ANNUAL REPORT   |                                       |      | Page 4      |
|---|---------------------------------------|------|-------------|
| OTHER INFORMATION  Please provide any comments of further information to be included as part of the Annual Report. Any other attachments are to be provided as Appendix E to this report. If information is submitted as a group rather then by individual mine, please identify each of the mine's data in the list below. |                                       |      |             |
| Additional attachment to this report?   | Yes                                   | No 🖂 |             |
|   |                                       |      |             |
|   |                                       |      | <u> </u>    |
|   |                                       |      |             |
|   |                                       |      |             |
|   |                                       |      |             |
|   |                                       |      |             |
|   |                                       |      |             |
|   |                                       |      |             |
|   |                                       |      |             |
|   | ·                                     |      |             |
|   |                                       |      |             |
|   |                                       |      |             |
|   |                                       |      |             |
|   |                                       |      |             |
|   |                                       |      |             |
|   |                                       |      |             |
|   |                                       |      |             |
|   |                                       |      |             |
|   | · · · · · · · · · · · · · · · · · · · |      |             |
|   |                                       |      | <del></del> |

#### APPENDIX A

## **Certified Reports**

Excess Spoil Piles Refuse Piles Impoundments

As required under R645-301-514

**CONTENTS** 

## **ANNUAL IMPOUNDMENT INSPECTIONS**

#### ANDALEX RESOURCES, INC. 2006 ANNUAL POND INSPECTION REPORT

| POND: _ | Sed. Basin "B" | LOCATION: | Centennial |
|---------|----------------|-----------|------------|
|         |                |           |            |

| IMPOUNDMENTS STATE OF THE PROPERTY OF THE PROP |   |  |
|--|---|--|
| (1) Stability  | Slopes Stable.  |  |
| (2) Structural Weakness/Erosion  | None Noted.   |  |
| (3) Potential Safety Hazards   | None Noted.   |  |
| (4) Depth of Impounded Water   | 12" Water - #2  |  |
| (5) Existing Storage Capacity  | 0.208 acre feet.  |  |
| (6) Monitoring Procedures  | Sediment Level. Cleanout at 50% accumulation. (Between 1 and 2) |  |

| SEDIMENT PONDS ONLY                              |                  |
|--|------------------|
| (7) Sediment Accumulation (Elevation)            | 7079.0 - #2      |
| (8) Sediment Cleanout Level (Elevation)          | 7081.0 - #2      |
| (9) Principle Spillway (Elevation)               | 7077.0 - #1      |
| (10) Emergency Spillway (Elevation)              | 7078.0 - #1      |
| (11) Existing Sediment Capacity<br>(To Cleanout) | 0.057 acre feet. |

| GENERAL                       | The Charles of the Ch |  |
|-------------------------------|--|--|
| (12) Comments/Recommendations | Cell B4 - Full (7091.0) Cell B3 - Full (7087.0) Cell B2 - 2.0' Remaining (7 Cell B1 - 5.1' Remaining (7 bottom below dike.   |  |

#### **STATEMENT**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

(Signature)

10/17/06 (Date)

#### ANDALEX RESOURCES, INC. 2006 ANNUAL POND INSPECTION REPORT

POND: Sed. Pond "C" LOCATION: Centennial

| IMPOUNDMENTS                    |                                 |  |
|---------------------------------|---------------------------------|--|
| (1) Stability                   | Slopes Stable.                  |  |
| (2) Structural Weakness/Erosion | None Noted.                     |  |
| (3) Potential Safety Hazards    | None Noted.                     |  |
| (4) Depth of Impounded Water    | Dry                             |  |
| (5) Existing Storage Capacity   | 2.99 acre feet.                 |  |
| (6) Monitoring Procedures       | U.P.D.E.S Quarterly Inspection. |  |

| SEDIMENT PONDS ONLY                              |                  |
|--|------------------|
| (7) Sediment Accumulation (Elevation)            | 7042.1           |
| (8) Sediment Cleanout Level (Elevation)          | 7046.9           |
| (9) Principle Spillway (Elevation)               | 7053.1           |
| (10) Emergency Spillway (Elevation)              | 7055.0           |
| (11) Existing Sediment Capacity<br>(To Cleanout) | 0.650 acre feet. |

| GENERAL                       |   |
|-------------------------------|---|
| (12) Comments/Recommendations | Pond Cleaned October 2006.<br>No Discharge. Inlets O.K. |

#### **STATEMENT**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

(Signature)

12/06/06
(Date)

#### ANDALEX RESOURCES, INC. 2006 ANNUAL POND INSPECTION REPORT

POND: Sed. Pond "E" LOCATION: Centennial

| IMPOUNDMENTS                    |                                  |  |  |  |  |
|---------------------------------|----------------------------------|--|--|--|--|
| (1) Stability                   | Slopes Stable.                   |  |  |  |  |
| (2) Structural Weakness/Erosion | None Noted.                      |  |  |  |  |
| (3) Potential Safety Hazards    | None Noted.                      |  |  |  |  |
| (4) Depth of Impounded Water    | 4.5' Water.                      |  |  |  |  |
| (5) Existing Storage Capacity   | 1.487 acre feet.                 |  |  |  |  |
| (6) Monitoring Procedures       | U.P.D.E.S. Quarterly Inspection. |  |  |  |  |

| SEDIMENT PONDS ONLY                              |                  |
|--|------------------|
| (7) Sediment Accumulation (Elevation)            | 6945.9           |
| (8) Sediment Cleanout Level (Elevation)          | 6946.5           |
| (9) Principle Spillway (Elevation)               | 6957.6           |
| (10) Emergency Spillway (Elevation)              | 6958.6           |
| (11) Existing Sediment Capacity<br>(To Cleanout) | 0.063 acre feet. |

| GENERAL                       |  |
|-------------------------------|--|
| (12) Comments/Recommendations | No Discharge. Inlets O.K. Outlets O.K. |

#### **STATEMENT**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

(Signature) 10/17/06 (Date)



#### APPENDIX B

## Reporting of Technical Data

Including monitoring data, reports, maps, and other information As required under the approved plan or as required by the Division

In accordance with the requirement of R645-310-130 and R645-301-140

**CONTENTS** 

#### **SUBSIDENCE MONITORING**

## TOWER RESOURCES, INC.

**2006 SUBSIDENCE SURVEY** 

10/30/2006

|                | NORTHING   | EASTING      | 2005      | 2006      | NOTES            |
|----------------|------------|--------------|-----------|-----------|------------------|
| STATION        | (FEET)     | (FEET)       | ELEVATION | ELEVATION |                  |
| Rebar on ridge | 505,141.92 | 2,217,261.07 | 8,241.62  | 8,241.62  | CONTROL          |
| Yellow Rebar   | 507,073.59 | 2,223,128.18 | 8,534.90  | 8,534.90  | CONTROL          |
| S-10           | 507,824.28 | 2,217,196.61 | 8,594.59  | 8,594.59  | CONTROL          |
| 1              | 511,963.35 | 2,216,981.20 | 8,509.59  | 8,509.63  | 1/2" rebar w/cap |
| 2              | 512,062.12 | 2,216,965.01 | 8,503.78  | 8,503.80  | 1/2" rebar w/cap |
| 3              | 512,165.33 | 2,216,978.66 | 8,496.82  | 8,496.84  | 1/2" rebar w/cap |
| 4              | 512,263.52 | 2,217,010.76 | 8,486.13  | 8,486.14  | 1/2" rebar w/cap |
| 5              | 512,367.50 | 2,217,038.78 | 8,473.91  | 8,473.89  | 1/2" rebar w/cap |
| 6              | 512,490.58 | 2,217,143.42 | 8,461.52  | 8,461.51  | 1/2" rebar w/cap |
| 7              | 512,589.90 | 2,217,213.86 | 8,453.25  | 8,453.25  | 1/2" rebar w/cap |
| 8              | 512,692.18 | 2,217,262.33 | 8,445.26  | 8,445.25  | 1/2" rebar w/cap |
| 9              | 512,800.40 | 2,217,300.21 | 8,436.64  | 8,436.66  | 1/2" rebar w/cap |
| 10             | 512,891.71 | 2,217,336.16 | 8,430.74  | 8,430.79  | 1/2" rebar w/cap |
| 11             | 513,000.47 | 2,217,368.65 | 8,424.38  | 8,424.43  | 1/2" rebar w/cap |
| 12             | 513,103.93 | 2,217,402.82 | 8,416.62  | 8,416.64  | 1/2" rebar w/cap |
| 13             | 513,196.61 | 2,217,451.14 | 8,408.31  | 8,408.36  | 1/2" rebar w/cap |
| 14             | 513,295.64 | 2,217,494.35 | 8,393.48  | 8,393.50  | 1/2" rebar w/cap |
| 15             | 513,371.68 | 2,217,541.37 | 8,380.48  | 8,380.51  | 1/2" rebar w/cap |
| 16             | 513,462.85 | 2,217,588.68 | 8,368.30  | 8,368.34  | 1/2" rebar w/cap |
| 17             | 513,556.68 | 2,217,641.91 | 8,360.76  | 8,360.76  | 1/2" rebar w/cap |
| 18             | 513,635.51 | 2,217,689.80 | 8,360.47  | 8,360.47  | 1/2" rebar w/cap |
| 19             | 513,711.41 | 2,217,742.70 | 8,356.49  | 8,356.52  | 1/2" rebar w/cap |
| 20             | 513,820.43 | 2,217,768.54 | 8,346.15  | 8,346.17  | 1/2" rebar w/cap |
| 21             | 513,912.62 | 2,217,806.85 | 8,331.93  | 8,331.92  | 1/2" rebar w/cap |
| 22             | 513,997.37 | 2,217,848.12 | 8,315.25  | 8,315.22  | 1/2" rebar w/cap |
| 23             | 514,100    | 2,217,900    | 8,298.55  | 8,298.52  | 1/2" rebar w/cap |
| 24             | 514,250    | 2,218,000    | 8,286.01  | 8,285.97  | 1/2" rebar w/cap |
| 25             | 514,400    | 2,218,150    | 8,273.43  | 8,273.39  | 1/2" rebar w/cap |
| 26             | 514,500    | 2,218,200    | 8,256.00  | 8,255.95  | 1/2" rebar w/cap |



## WARE SURVEYING & ENGINEERING



## TOWER RESOURCES, INC. 2006 SUBSIDENCE SURVEY

9/25/2006

|                |            |              |           |           |           |           | 9/25/2000 |
|----------------|------------|--------------|-----------|-----------|-----------|-----------|-----------|
|                | NORTHING   | EASTING      | 2003      | 2004      | 2005      | 2006      | NOTES     |
| STATION        | (FEET)     | (FEET)       | ELEVATION | ELEVATION | ELEVATION | ELEVATION |           |
| Rebar on ridge | 505,141.92 | 2,217,261.07 | 8,241.62  | 8,241.62  | 8,241.62  | 8,241.62  | CONTROL   |
| Yellow Rebar   | 507,073.59 | 2,223,128.18 | 8,534.90  | 8,534.90  | 8,534.90  | 8,534.90  | CONTROL   |
| S-10           | 507,824.28 | 2,217,196.61 | 8,594.59  | 8,594.59  | 8,594.59  | 8,594.59  | CONTROL   |
| 1A             | 504,057.58 | 2,216,580.88 | 8,147.07  | 8,147.01  | 8,147.01  | 8,147.02  |           |
| 1              | 502,940.63 | 2,216,278.86 | 8,178.03  | 8,177.98  | 8,177.99  | 8,177.97  | ***       |
| 4              | 503,238.22 | 2,221,322.25 | 8,285.02  | 8,284.77  | 8,284.76  | 8,284.74  | -         |
| 11             | 498,938.93 | 2,218,688.76 | 7,671.20  | 7,671.22  | 7,671.22  | 7,671.19  |           |
| 9              | 506,252.80 | 2,221,663.53 | 8,544.02  | 8,544.05  | 8,543.98  | 8,543.95  |           |
| 5              | 504,194.65 | 2,224,746.94 | 8,001.92  | 8,001.90  | 8,001.89  | 8,001.89  |           |
| 7              | 502,013.34 | 2,225,964.02 | 8,102.98  | 8,102.98  | 8,102.99  | 8,102.97  |           |
| 13             | 500,747.06 | 2,228,007.66 | 7,854.72  | 7,854.67  | 7,854.65  | 7,854.63  |           |
| S31            | 506,352.97 | 2,217,376.82 | 8,386.64  | 8,386.51  | 8,386.52  | 8,386.51  |           |
| S30            | 506,015.07 | 2,215,357.70 | 8,118.02  | 8,117.88  | 8,117.86  | 8,117.87  |           |
| S16            | 508,650.48 | 2,210,725.70 | 8,809.53  | 8,809.58  | 8,809.66  | 8,809.64  |           |
| S17            | 508,190.63 | 2,213,802.51 | 8,624.48  | 8,624.50  | 8,624.51  | 8,624.46  |           |
| 99-1           | 508,942.12 | 2,215,063.90 | 8,572.35  | 8,572.32  | 8,572.26  | 8,572.17  | ***       |
| 99-2           | 509,023.29 | 2,218,624.20 | 8,551.12  | 8,551.01  | 8,551.03  | 8,550.95  |           |
| S20            | 510,331.29 | 2,217,642.56 | 8,574.26  | 8,574.07  | 8,574.07  | 8,573.90  |           |
| S21            | 510,581.75 | 2,214,956.87 | 8,489.90  | 8,490.02  | 8,489.80  | 8,489.37  |           |
| S32            | 509,739.02 | 2,218,933.12 | 8,548.93  | 8,548.88  | 8,548.85  | 8,548.78  | ***       |



# WARE SURVEYING & ENGINEERING G.P.S. & CONVENTIONAL SURVEYING - AUTOCAD MAPPING - CIVIL ENGINEERING



#### APPENDIX C

## Legal Financial, Compliance and Related Information

Annual Report of Officers As submitted to the Utah Department of Commerce

Other change in ownership and control information
As required under R645-301-110

**CONTENTS** 

**ON FILE** 

#### APPENDIX D

Mine Maps

As required under R645-302-525-270

**CONTENTS** 

ABERDEEN MINE AND PINNACLE MINE

#### APPENDIX E

## Other Information

In accordance with the requirements of R645-301 and R645-302

**CONTENTS** 

N/A